## **CORNER RECORD**

## **COUNTY OF PLACER, CALIFORNIA**

SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act  on December 5, 20 12  Signed Record A Monúco  L.S. Number 6376  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 and examined and filed December 26, 2013 20	0076
T. 11 N Government Corner Control N Surveyors' Act  R. 7 E Rancho Other Zone Datur  Corner Left as found Found and tagged Stablished Reestablished  Identification and type of corner found: Evidence used to identify or procedure used to establish or reests. The original iron pipe set at the sideline angle point common to Lots 5/6 was destroyed during fence of All other record monuments for Lot 5 were recovered and checked.  A description of the physical condition of the monument as found and as set or reset:  No physical evidence of the original pipe was found. A wood fence post now occupies the position of the point. A nail and brass tag, L.S. 6376, was set in the top of a 4"x4" wood fence post at the position of the point.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act  on December 5, 20 12  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 20 20 20 20 20 20 20 20 20 20 20 20	
Identification and type of corner found: Evidence used to identify or procedure used to establish or reesta. The original iron pipe set at the sideline angle point common to Lots 5/6 was destroyed during fence concentration.  A description of the physical condition of the monument as found and as set or reset:  No physical evidence of the original pipe was found. A wood fence post now occupies the position of the point. A nail and brass tag, L.S. 6376, was set in the top of a 4"x4" wood fence post at the position of the point.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act  on December 5, 20 12  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 20 20 20 20 20 20 20 20 20 20 20 20	onal)
The original iron pipe set at the sideline angle point common to Lots 5/6 was destroyed during fence of All other record monuments for Lot 5 were recovered and checked.  A description of the physical condition of the monument as found and as set or reset:  No physical evidence of the original pipe was found. A wood fence post now occupies the position of the point. A nail and brass tag, L.S. 6376, was set in the top of a 4"x4" wood fence post at the position of the point.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act  on December 5, 20 12  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20  and examined and filed December 26, 2013 20	Rebuilt
No physical evidence of the original pipe was found. A wood fence post now occupies the position of the point. A nail and brass tag, L.S. 6376, was set in the top of a 4"x4" wood fence post at the position of the point.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act  on December 5, 20 12  Ruinul A Monico  L.S. Number 6376  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20  and examined and filed December 26, 2013 20	
This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on December 5, 20 12 Signed Record A Montio  L.S. Number 6376  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 20 20 20 20 20 20 20 20 20 20 20 20	······································
on December 5, 20 12  Signed Richard A Monino  L.S. Number 6376  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 and examined and filed December 26, 2013 20	e/
COUNTY SURVEYOR'S STATEMENT  This Corner Record was received 20 and examined and filed December 26, 2013 20	
and examined and filed DECETAREN 26, 2013 20 20	•
Signed Shis Husbern Title DEDUTY COUNTY Surveyor  L.S. or R.O.E. Number 6584 Exp. 12-31-2013  Exp. 12-31-2013  County Surveyor's Comment	
County Surveyor's Comment	

