


CORNER RECORD

Document Number _____

City of _____ County of PLACER, California

Brief Legal Description LOT 1, BLOCK 3, CEDAR FLAT SUBDIVISION, H/MAPS/82, O.R.P.C.



SEC. 28

T. 16 N.

R. 17 E.

M.D.B.;M.

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey 8-8-2006

COORDINATES (Optional)

- N. _____
- E. _____
- Zone NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED THE RECORD DIMENSIONS AND THE FOUND ORIGINAL MONUMENTS PER H/MAPS/82, O.R.P.C., TO REESTABLISH THE MISSING CORNERS OF LOT 1, BLOCK 3, AS SHOWN ON THE ACCOMPANYING PLAT.


A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR WITH YELLOW PLASTIC CAP MARKED LS 7429.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on August 09 2006

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 09-18-07

and examined and filed OCT. 18 2007

Signed Charles B. Grant P.L.S. or R.C.E. No. 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____





BOOK 10 CORNER RECORDS PAGE 88

PLAT OF SURVEY

LOT 1, BLOCK 3, CEDAR FLAT SUBDIVISION, BOOK H, OF MAPS AT PAGE 82, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF THE N.E. 1/4 OF SECTION 28, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 8/8/2006



NOTE:

ALL BEARINGS AND DISTANCES SHOWN HEREON ARE RECORD PER H/MAPS/82, O.R.P.C.

- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1288.00

BOOK 1D CORNER RECORDS PAGE 88