


CORNER RECORD

Document Number 09-03

City of _____ County of SUTTER, California

Brief Legal Description CORNER COMMON TO SEC. 12, 13 T. 12 N. R. 5 E., AND SEC. 7, 18 T. 12 N., R. 5 E.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey DECEMBER, 2009

COORDINATES (Optional)

N. 2088910.622
 E. 6772684.083
 Zone 2 NAD27 NAD83
 NAD83 Epoch 2007
 Elev. 60.95
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPE PER PARCEL MAP #211 - REPLACED AS DESCRIBED BELOW

A description of the physical condition of the monument as found and as set or reset:
NEW 2 1/2" BRASS DISC SET IN MONUMENT WELL STAMPED SCPW & RELEVANT INFORMATION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DECEMBER 29, 2009
 Signed Jerry Orr P.L.S. or R.C.E. No. 21203



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 29, 2009
 and examined and filed DECEMBER 29, 2009
 Signed Jerry Orr P.L.S. or R.C.E. No. 21203
 Title COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 13 CORNER RECORDS, PAGE 82