


CORNER RECORD

Document Number _____

City of _____ County of PLACER, California

Brief Legal Description LOT 6, PINELAND UNIT NO. 2 SUBDIVISION, E/MAPS/77, O.R.P.C.



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 7-13-2005

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSIONS AND FOUND MONUMENTS PER E/MAPS/77, O.R.P.C., TO REESTABLISH THE MISSING NORTH EAST CORNER OF LOT 6 AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR WITH YELLOW PLASTIC CAP MARKED L.S. 7429

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 7/20/05

Signed [Signature] P.L.S or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 12TH 2005

and examined and filed AUGUST 23 2005

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

BOOK 10 CORNER RECORDS PAGE 3

PLAT OF SURVEY

LOT 6, PINELAND UNIT NO. 2 SUBDIVISION, BOOK E OF MAPS AT PAGE 77, OFFICIAL RECORDS PLACER COUNTY CALIFORNIA, A PORTION OF THE N.W. 1/4 OF SECTION 24, TOWNSHIP 15, N., RANGE 16, E., M.D.B.& M.

SCALE 1" = 40' DATE OF SURVEY 7/13/2005



NOTE:

ALL BEARINGS AND DISTANCES SHOWN HEREON ARE RECORD PER E/MAPS/77, O.R.P.C.

- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1047.00

BOOK 10 CORNER RECORDS PAGE 3