


CORNER RECORD

Document Number _____

City of UNINCORPORATED AREA County of PLACER, CaliforniaBrief Legal Description PARCEL "A" BOOK 2 OF PARCEL MAPS PAGE 107 P.C.R.

SEG. 15
T. 17 N.
R. 16 E.
M. O. M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 10/25/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND 5/8" REBAR PER H/MAPS/50, UNLESS OTHERWISE NOTED
- = FOUND 1" IRON PIPE W/PLASTIC PLUG, L.S. 5549
- = FOUND 3/4" IRON PIPE W/PLASTIC PLUG, R.C.E. 9896

A description of the physical condition of the monument as found and as set or reset:

○ = SET 1" IRON PIPE W/PLASTIC PLUG L.S. 5549

JN. 05136

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on OCTOBER 26, 2005

Signed Charles R. Sage Jr. P.L.S or R.C.E. No. L.S. 5549
 LIC. EXP. 6/30/07

**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed Nov. 7, 2006

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER 2/PM/107 AND 'H'/MAPS/50 P.C.R.
 NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

SCALE 1"=50'

SILVERFIR DRIVE (V5036)

