


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description Lot 15, Block A, Forest Glen Sub. F/MAPS/21
O.R.P.C.



Sec. 28
T. 16N
R. 16E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/12/2006

COORDINATES (Optional)

~~N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial~~

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Used Record Dimension & Monuments to
reestablish the missing corners of Lot 15
Per F. /MAPS/21. O.R.P.C. AS Shown on
the Accompanying Plat.

A description of the physical condition of the monument as found and as set or reset:


Set 5/8" Rebar with yellow plastic
cap. L.S. 7429.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 13 2006

Signed [Signature] P.L.S. or R.C.E. No. 7429




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed AUG. 3, 2007

Signed [Signature] P.L.S. or R.C.E. No. 6158

Title DEPUTY COUNTY SURVEYOR LICENSE EXPIRES 3-31-08





County Surveyor's Comment _____

BOOK 10 CORNER RECORDS PAGE 71

PLAT OF SURVEY

LOT 15, BLOCK "A", FOREST GLEN SUBDIVISION,
 BOOK F, OF MAPS AT PAGE 21, OFFICIAL RECORDS
 PLACER COUNTY, CALIFORNIA. A PORTION OF THE
 N.W. 1/4 OF SECTION 28, TOWNSHIP 16 N., RANGE
 16 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 7/12/2006



- (R) RECORD PER F/MAPS/21, O.R.P.C..
- FOUND MONUMENT AS SHOWN HEREON
- ⊗ SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1265.00

BOOK 10 CORNER RECORDS PAGE 71