


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description LOT 110, SERENE LAKES UNIT No's 5 & 6, J/MAPS/67, O.R.P.C.



SEC. 27
T. 17 N.
R. 14 E.
M.D.B. & M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 5-24-2007

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED THE RECORD DIMENSIONS AND THE FOUND ORIGINAL MONUMENTS PER J/MAPS/67, O.R.P.C., TO REESTABLISH THE MISSING CORNERS FOR LOT 110, AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:


SET 5/8" REBAR WITH YELLOW PLASTIC CAP MARKED LS 7429, AND SET A NAIL AND BRASS TAG MARKED LS 7429 IN A UTILITY BOX.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on May 29, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed Nov. 29, 2007

Signed [Signature] P.L.S. or R.C.E. No. LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____





BOOK 14 CORNER RECORDS PAGE 20

PLAT OF SURVEY

LOT 110, SERENE LAKES UNIT 5 & 6 SUBDIVISION, BOOK J OF MAPS AT PAGE 67, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF THE N.E. 1/4 OF SECTION 27, TOWNSHIP 17 N., RANGE 14 E., M.D.B. & M.

SCALE 1" = 30' DATE OF SURVEY 5/24/2007



NOTE:

- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429 UNLESS OTHERWISE NOTED HEREON
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1446.00

BOOK 11 CORNER RECORDS PAGE 20