


CORNER RECORD

Document Number 20130037

City of Carnelian Bay County of PLACER, California

Brief Legal Description Lot 15, Carnelian Heights Unit #1/ Placer County, CA., Bk G/Subdivisions/Pg.23



CORNER TYPE

COORDINATES (Optional)

- Government Corner Control
 Meander Property
 Rancho Other

N. _____
 E. _____
 Zone _____ Datum _____

T.16 N., R.17 E., MDM Date of Survey May 8 and May 11, 2013 Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS AS SHOWN ON PAGE 2

USED NEAREST FOUND MONUMENTS WITHIN UNIT TO REESTABLISH PROPERTY

CORNERS AS SHOWN HEREON.

FOUND MONUMENTS IN GOOD CONDITION EXCEPT AS NOTED.

A description of the physical condition of the monument as found and as set or reset: _____

SET MONUMENT AS SHOWN ON PAGE 2

PLACED WOOD LATH AT SET AND FOUND MONUMENTS OF SUBJECT PROPERTY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 1 2013.

Signed [Signature] L.S. or R.C.E. Number R.C.E. 20257



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined and filed June 17th 2013.

Signed [Signature: Leslie Amsherry] Title Deputy County Surveyor

County Surveyor's Comment : _____



BOOK 16 OF CORNER RECORDS, PAGE 20

BOOK 16 OF COLLIER RECORDS PAGE 20

NOTES:

- BEARINGS AND DISTANCES ARE RECORD PER G/MAPS/23
- FOUND 1/2" REBAR PER G/MAPS/23
- Ⓞ FOUND 3/8" REBAR W/PLASTIC CAP TAGGED LS3422 PER 5/CR/076
- Ⓞ FOUND 1/2" REBAR W/PLASTIC CAP LS 4029 PER 4/CR/051
- SET 5/8" REBAR W/PLASTIC CAP RCE 20257
- ⑮ LOT NUMBER PER G/MAPS/23



1"=50'

